

Video Survey Field Sheet

TRAFSTATS PROJECT #

SURVEY DATE

05-183

8-6-05

LOCATION:

US 101 / Glenden
Beach Rd - Walker

MAP PAGE

GRID


CITY:

Siletz Bay, OR

TIME

3p - 5p

WEATHER: ☒ Sunny ☐ Overcast ☐ Rain ☐ Snow ☐ Fog



CAMERA -A

R

Number

C14

Start 1st Film

Date:

8-6-05

Time:

12:26

Film:

T84

Batt:

B34

Start 2nd Film

Date:

Time:

Film:

Batt:

Start 3rd Film

Date:

Time:

Film:

Batt:

Start 4th Film

Date:

Time:

Film:

Batt:

Start 5th Film

Date:

Time:

Film:

Batt:

CAMERA -B

R

Number

Start 1st Film

Date:

Time:

Film:

Batt:

Start 2nd Film

Date:

Time:

Film:

Batt:

Start 3rd Film

Date:

Time:

Film:

Batt:

Start 4th Film

Date:

Time:

Film:

Batt:

Start 5th Film

Date:

Time:

Film:

Batt:

REMARKS:

Surveyed By:

KBA



TRAFSTATS

1225 SW Murray Rd Suite 110
Portland, OR 97229



Intersection Turning Movement Summary Report

Location US 101 AT GLENEDEN BEACH ROAD
Date 8/6/2005
Day of Week Saturday
Time Begin 15:00
Reviewed By: BV

Time Period	Eastbound			Westbound			Northbound			Southbound			Totals
	Right	Thru	Left	Right	Thru	Left	Right	Thru	Left	Right	Thru	Left	
15:00 - 15:15	0	0	19	0	0	0	0	195	2	20	212	0	448
15:15 - 15:30	3	0	19	0	0	0	0	226	3	31	219	0	501
15:30 - 15:45	4	0	14	0	0	0	0	201	0	27	215	0	461
15:45 - 16:00	2	0	11	0	0	0	0	212	6	25	196	0	452
16:00 - 16:15	3	0	15	0	0	0	0	209	4	11	189	0	431
16:15 - 16:30	3	0	9	0	0	0	0	207	3	23	207	0	452
16:30 - 16:45	3	0	9	0	0	0	0	196	7	26	212	0	453
16:45 - 17:00	2	0	13	0	0	0	0	230	3	19	204	0	471
Movement Totals	20	0	109	0	0	0	0	1676	28	182	1654	0	3669
Enter Totals	129			0			1704			1836			
Exit Totals	0			210			1785			1674			

Two-Hour Totals

Light Trucks	0	0	1	0	0	0	0	25	0	1	35	0	62
Medium Trucks	0	0	0	0	0	0	0	0	0	0	2	0	2
Heavy Trucks	0	0	0	0	0	0	0	3	0	0	3	0	6
% Trucks	0.0%	NA	0.9%	NA	NA	NA	NA	1.7%	0.0%	0.5%	2.4%	NA	1.9%
Buses	0	0	0	0	0	0	0	0	0	0	0	0	0
Bicycles	0	0	0	0	0	0	0	0	0	0	2	0	2

	South	West	East	North	
Pedestrians	0	1	0	0	1

Peak Hour Information

Peak Hour 15:00 16:00

	Eastbound			Westbound			Northbound			Southbound			Totals
	Right	Thru	Left	Right	Thru	Left	Right	Thru	Left	Right	Thru	Left	
Movement Total	9	0	63	0	0	0	0	834	11	103	842	0	1862
Peak Hour Factor	0.56	NA	0.83	NA	NA	NA	NA	0.92	0.46	0.83	0.96	NA	0.93

Enter Totals	72			945			845			0			
Peak Hour Factor	0.82			0.95			0.92			NA			

Exit Totals	0			851			897			114			
Peak Hour Factor	NA			0.96			0.92			0.84			

Light Trucks	0	0	0	0	0	0	0	9	0	0	20	0	29
Medium Trucks	0	0	0	0	0	0	0	0	0	0	0	0	0
Heavy Trucks	0	0	0	0	0	0	0	1	0	0	2	0	3
% Trucks	0.0%	NA	0.0%	NA	NA	NA	NA	1.2%	0.0%	0.0%	2.6%	NA	1.7%
Buses	0	0	0	0	0	0	0	0	0	0	0	0	0
Bicycles	0	0	0	0	0	0	0	0	0	0	0	0	0

	South	West	East	North	
Pedestrians	0	1	0	0	1

Intersection Turning Movement Peak Hour Diagram

Location US 101 AT GLENEDEN BEACH ROAD

Date 8/6/2005

Day of Week Saturday

Time Begin 15:00

Reviewed By: BV

